

Fix form Rev.2.0
 R25 10KΩ = 100Ω
 C29 C30 C32 0.1uF = 0.01uF
 Sw1 = Point_Sw1 Port move
 Sw2 = Point_Sw2 Port move
 10KΩ x 3 ??

